

OFFICE OF THE SUB DIVISIONAL ENGINEER, PROVINCIAL SUB DIVISION NO. III, PWD B&R BR., KURUKSHETRA

To

The Executive Engineer
Provincial Division No 1
PWD, B&R Branch, Kurukshetra.

No. 399 Dated: 01/04/2026

Subject: Regarding renewal of school building safety certificate.
(Sahara Comprehensive School, Amin Road, Distt. Kurukshetra)
Reference: Your good office Endst. no. 381 dated 04.02.2025.

In this connection, it is submitted that the school building of Sahara Comprehensive School, Amin Road, Distt. Kurukshetra has been inspected by I.E in charge of this office and found that the School Building seems to be safe as per visual inspection of the structure. Therefore, it is recommended that the safety certificate may be issued. This is for your kind information & further necessary action please.

DA/NI

SW
Sub Divisional Engineer
Provincial Sub Division No. 3,
PWD B&R Br. Pipli, KKR

Manager *[Signature]*
Sahara Comprehensive School
Amin Road, Kurukshetra

[Signature]
Principal
Sahara Comprehensive School
Amin Road, Kurukshetra-136119
Ph. 99965-90400

Saujika
3/04/26



HARYANA PWD (B&R)
EXECUTIVE ENGINEER,
Provincial Division No.1,
PWD B&R, Kurukshetra-136118.
Ph. No. (01744-239442)
Email ID- pwd-eepd1-kurukshetra@hrv.nic.in

To

The Principal
Sahara Comprehensive School
Amin Road, Kurukshetra

No. 1679


Dated: 20-4-26

Subject: Regarding issuance of Building Safety Certificate

Reference: Your office letter dated 29.1.2026

In this connection, it is submitted that the building of Sahara Comprehensive School, Amin Road, Kurukshetra has been inspected by the Sub-Division No.3, PWD B&R, Pipli along with concerned Junior Engineer and building found to be safe as per visual inspection of the structure of the building. The school Building Safety Certificate is hereby given upto the period 02/2026 to 02/2027 with the following conditions:-

1. Building of this school should be repaired every year.
2. Water should not be allowed to stagnate around and on the roof of the Building.
3. If Building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
4. Institution will be responsible for safety of building from every angle and Fire-Fighting equipment should be in functional condition.
5. If the building of the school is to be extended, the same should be first approved from Structural Engineer.
6. Adequate Fire safety may be adopted in the school campus.
7. Institute shall also ensure safety precautions from false ceiling and vitrified tiles used in dado.
8. NOC may be considered as cancelled by this office if the college violates any of the above points.



Executive Engineer,
Provincial Division No.1,
PWD B&R, Kurukshetra

DA/Nil
Endst No. Dated

Copy forwarded to the SDE, PSD-3, PWD B&R, Pipli for information w.r.t letter No. 399 dated 1.4.2026.

DA/Nil

Executive Engineer,
Provincial Division No.1,
PWD B&R, Kurukshetra

Manager 
Sahara Comprehensive School
Amin Road, Kurukshetra


Principal
Sahara Comprehensive School
Amin Road, Kurukshetra-136119
Ph. 99965-90400